



PDI Roller

26 Aug 2026 / Andy Bunker / ROR 5

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
Conducted on	26 Aug 2026 8:00 AM BST				
Prepared by	Andy Bunker				
Location	Sunnyside Bedford England MK45 5AH United Kingdom				
Asset	ROR 5 Roller - Hamm 120 Roller - 12VV				

Untitled Page	
MACHINE CONDITION	
Machine clean & presentable	Pass
No major damage to bodywork	Pass
Decals & safety stickers fitted	Pass
Engine covers secure	Pass
Handrails & steps secure	Pass
Mirrors fitted & secure	N/A
Beacon fitted & working	Pass
ENGINE COMPARTMENT	
Engine oil level	Pass
Coolant level	Pass
Hydraulic oil level	Pass
Fuel level	Pass
No fuel leaks	Pass
No oil leaks	Pass
Air filter condition	Pass
Battery secure	Pass
DRUMS & WATER SYSTEM	
Front drum condition	Pass
Rear drum condition	Pass
Drum scrapers adjusted	Pass
Spray bars clean	Pass
Water tank full	N/A

Water spray working	Pass
Water pump operating	Pass
HYDRAULICS	
No hydraulic leaks	Pass
Hoses in good condition	Pass
Fittings secure	Pass
ELECTRICAL	
Headlights	Pass
Work lights	Pass
Indicators [if fitted]	Pass
Reverse alarm	Pass
Horn	Pass
Instrument display	Pass
Warning lights operate correctly	Pass
OPERATOR STATION	
Seat condition	Pass
Seat belt operational	Pass
Steering smooth	Pass
Controls labelled	Pass
Emergency stop (if fitted)	Pass
Fire extinguisher fitted (if required)	N/A
FUNCTIONAL TEST	
Engine starts easily	Pass
No abnormal smoke	Pass

Machine drives forward	Pass
Machine drives reverse	Pass
Steering operates correctly	Pass
Brake operates correctly	Pass
Parking brake holds machine	Pass
Vibration front drum	Pass
Vibration rear drum	Pass
High/low vibration selection	Pass
Water spray on all settings	Pass
Travel speed functions correctly	Pass
FINAL CHECKS	
Grease points serviced	Pass
Tyres (if pneumatic rear model) / drums clean	N/A
Machine Cleaned	Pass
comments/defects	☐
Item of plant ready for site	Yes

Photos of asset [please take pics from all 4 sides]



Photo 1



Photo 2



Photo 3



Photo 4

Signature:

Andy b
26 Aug 2026 8:02 AM BST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4