Record No: 2024/11/406/124881

## RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT AND EQUIPMENT

IN ACCORDANCE WITH THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

Doosan DX140LC-7	
Doosan DX 140LC-7	
Pno ASH 1410 Sno DXCCEBDTAN0020207	
Geith 1126711	
Ashvale Plant Hire Ltd	
Firbank Trading Estate	
Luton	
LU1 1TD	
November 2023	
Refer to Manufacturers Lifting Charts & Radii Tables	
None	
Enclosed parts of hydraulic system	
28th November 2025	
20° November 2025	
Wing Road, Stewkley, Leighton Buzzard, LU7 0JB	
Willig Road, Stewkiey, Leighton Buzzard, Eo7 03B	
Always ensure that the correct operators instructions are with the	
machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.	
	THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO I

## Declaration

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on 28/11/2024 and that the above particulars are correct.

Signature or other identification

Illentee\_

Allen Lee. Engineering Surveyor

Name and address of person authenticating the record and responsible for the thorough examination.

Sky Technical Services Ltd

4 Victoria Cottages

Love Lane, Mayfield, E.Sussex. TN20 6EN.

Tel 01435 873355 / 07703 292932.

Email info@skytechnical.co.uk

Date the record is made 28/11/2024