Record Of Thorough Examination Of Lifting Plant & Equipment

ASH 29

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0

000030

Conducted on	23 Sep 2026 2:36 PM BST
Prepared by	A bunker
Location	Moxon street barnet
Asset	ASH 29 14 Ton Excavator - Excavator Doosan DX140LC-7
Asset serial number	20200
Identification mark of quick hitch & model	Geith serial unknown
Date of the last thorough examination	10/09/2025

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE)	None
Date(s) by which defects described above must be rectified	
Latest date by which the next thorough examination must be carried out	23 Sep 2027 2:38 PM BST

Supply multiple photo's of asset - all sides, any damage etc


Photo 1


Photo 2


Photo 3


Photo 4


Photo 5


Photo 6


Photo 7


Photo 8


Photo 9

Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name Andy bunker

Engineers signature



Andy bunker
23 Sep 2026 2:39 PM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8


CE
UK
CA
Machine Type
Model Name
Product Identification Number
Engine Power kW
Year of Construction
Operating Mass kg
First Year of Service
Hyundai Doosan Infracore Co. Ltd
489, Injung-Ro, Dong-gu,
Incheon, Korea
95205-07844B

Photo 9