



1.ASHVALE PLANT WORKSHEET

ASH 913

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
-------	------------	---------------	---	---------	---

Site conducted

Ashvale Head Office

Conducted on

4 Jun 2026 1:55 PM BST

Location

Sunnyside, Toddington Rd,
Westoning, Bedford MK45 5AH,
UK

Asset number/registration

ASH 913

Asset hours/vehicle mileage

Job description/additional notes

PDI INSPECTION

Parts used

Supply multiple photo's of asset, showing all sides and any damage



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Media summary



Photo 1



Photo 2



Photo 3




Photo 4



Photo 5