



Record Of Thorough Examination Of Lifting Plant & Equipment

Ash 38

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
-------	------------	---------------	---	---------	---

000026

Conducted on 12 Aug 2026 9:46 AM BST

Prepared by Andy bunker

Location Sunnyside
Bedford England MK45 5AH
United Kingdom

Asset Ash 38
3 Ton Excavator - Excavator (Mini)
Kubota KX027-4

Asset serial number 58444

Identification mark of quick hitch & model Whites manual

Date of the last thorough examination

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE) None

Date(s) by which defects described above must be rectified

Latest date by which the next thorough examination must be carried out 12 Aug 2027 9:48 AM BST

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Always ensure that the correct operators instructions are with the machine and that the correct

SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name

Andy bunker

Engineers signature



Andy bunker
12 Aug 2026 9:49 AM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5