



## 2.CERTIFICATE OF EXAMINATION

ROR 7

Complete

Score	55 / 56 (98.21%)	Flagged items	0	Actions	0
-------	------------------	---------------	---	---------	---

Site conducted

BH004 Loverose Way, Wixams,  
Vistry Homes

Conducted on

12 Nov 2025 10:54 AM GMT

Prepared by

Andy Bunker

Location

(52.0855582, -0.4805535)

Asset

ROR 7  
Roller - Hamm H7i Padfoot Roller

Asset serial number

2347

Asset hours

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2

Power unit	11 / 11 (100%)
Oil level	Acceptable
Water/Antifreeze level	Acceptable
Belt tension/Condition	Acceptable
Mountings	Acceptable
Emissions/Exhaust	Acceptable
Oil leaks	Acceptable
Hoses & pipes	Acceptable
Gauges/Warning indicators	N/A
Turbo	Acceptable
Air cleaner/Indicator	Acceptable
Spark Arrestor	N/A

<b>Transmission</b>	5 / 5 (100%)
<b>Oil levels/Leaks</b>	Acceptable
<b>Controls/Operations</b>	Acceptable
<b>Drive shafts/Axles</b>	Acceptable
<b>Hub reduction units/levels</b>	Acceptable
<b>Transfer box/levels</b>	Acceptable

<b>Brakes</b>	5 / 5 (100%)
<b>Air/Hydraulic leaks</b>	Acceptable
<b>Drums/Discs/Pads/Shoes</b>	Acceptable
<b>Foot/Hand controls</b>	Acceptable
<b>Cables/Rods/Pipes</b>	Acceptable
<b>Fluid levels/Efficiency</b>	Acceptable


Steering		6 / 6 (100%)
Box/Column/Wheel		Acceptable
King Pins/Bushes		Acceptable
Ramp/Pump/Hoses		Acceptable
Track Rods/Steering Arms		Acceptable
Linkages/Ball joints		Acceptable
Oil levels/Leakes		Acceptable

<b>Running Gear</b>		5 / 5 (100%)
<b>Tyres/Wheels/Tracks</b>		Acceptable
<b>Wheel bearings</b>		Acceptable
<b>Axle security</b>		Acceptable
<b>Over run brake rods/cable</b>		Acceptable
<b>Towing/Frame Attachments</b>		N/A

<b>Fuel System</b>	4 / 4 (100%)
<b>Fuel tank/Security</b>	Acceptable
<b>Fuel line/leaks</b>	Acceptable
<b>Filters/Pumps</b>	Acceptable
<b>Fuel level/Gauge</b>	Acceptable

<b>Hydraulics</b>		5 / 5 (100%)
<b>Rams</b>		Acceptable
<b>Pumps/Hoses/Pipes</b>		Acceptable
<b>Safety indicators</b>		Acceptable
<b>Oil levels/leaks</b>		Acceptable
<b>Controls</b>		Acceptable



<b>Electrical</b>	9 / 10 (90%)
<b>Battery</b>	Acceptable
<b>Alternator/Charging</b>	Acceptable
<b>Wiring</b>	Acceptable
<b>Fuses/Circuit breakers</b>	Acceptable
<b>Lights/Indicators</b>	Not Acceptable
Rear lights broken	
	
Photo 3	
<b>Warning Indicators</b>	Acceptable
<b>Outlet sockets</b>	N/A
<b>Limit/Proximity switches</b>	Acceptable
<b>Safety Devices</b>	Acceptable
<b>Warning Devices</b>	Acceptable

<b>Cab</b>	5 / 5 (100%)
<b>Seating/Belts</b>	Acceptable
<b>Structure/Rops</b>	Acceptable
<b>Glass/Mirrors</b>	Acceptable
<b>Mountings</b>	Acceptable
<b>Safe access to components, struts and hinges all in working order</b>	Yes

## Sign off

### Engineers name & signature



Andy Bunker  
12 Nov 2025 10:57 AM GMT

---

## Media summary



Photo 1



Photo 2



Photo 3