Record No: 2025/06/406/128332

RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT AND EQUIPMENT

IN ACCORDANCE WITH THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

Diesel Hydraulic Excavator
Kubota KX080-4A2
Pno ASH 827 Sno KBCDZ84BLP3B79847 Q/H Sno 122708
Ashvale Plant Hire Ltd
Firbank Trading Estate
Luton
LU1 1TD
NA
June 2024
Refer to Manufacturers Lifting Charts & Radii Tables
NI
None
Enclosed Parts of Hydraulic System
, ,
Eth Lucy 0000
5 th June 2026
a /a Didway sint Hawasa Must Enter from High Ctuart Chalavaya
c/o Ridgepoint Homes, Must Enter from High Street, Chalgrove, OX44 7AF
Always ensure that the correct operator's instructions are in the
machine and that the correct operator's instructions are in the machine and that the correct SWL is clearly visible. Where a quick hitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For Full SWL specifications always Refer to Manufacturers Lifting/Radii Tables

Declaration

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on **05/06/2025** and that the above particulars are correct.

Signature or other identification

Allen Lee. Engineering Surveyor

Mentee

Name and address of person authenticating the record and responsible for the thorough examination.

Sky Technical Services Ltd

4 Victoria Cottages

Love Lane, Mayfield, E. Sussex. TN20 6EN. Tel 01435 873355 / 07703 292932. Email info@skytechnical.co.uk

Date the record is made 05/06/2025