



Record Of Thorough Examination Of Lifting Plant & Equipment

ASH 828

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
-------	------------	---------------	---	---------	---

000022

Conducted on 24 Jul 2026 10:27 AM BST

Prepared by Andy bunker

Location 10-12 Rainbow Close
Bedford England MK45
United Kingdom

Asset ASH 828
8 Ton Excavator - Excavator
Kubota KX080-4a2

Asset serial number 79853

Identification mark of quick hitch & model Tefra serial unknown

Date of the last thorough examination 17/0725

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE) Mirror cracked

Date(s) by which defects described above must be rectified Within a week

Latest date by which the next thorough examination must be carried out 24 Jul 2027 10:30 AM BST

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name Andy bunker

Engineers signature



Andy bunker
24 Jul 2026 10:32 AM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7