Record Of Thorough Examination Of Lifting Plant & Equipment [LOLER]

ASH 833

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0

000032

Conducted on	6 Oct 2026 11:31 AM BST
Prepared by	BRANDON PERRY
Location	36 Whitings Rd, Barnet EN5 2QY, UK (51.6459561, -0.2180599)
Asset	ASH 833 8 Ton Excavator - Excavator Kubota KX085-5
Asset serial number	KBCDZ85BEP3F10380
Identification mark of quick hitch & model	N/A
Date of the last thorough examination	N/A

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE)	NONE
Date(s) by which defects described above must be rectified	
Latest date by which the next thorough examination must be carried out	6 Oct 2027 11:32 AM BST

Supply multiple photo's of asset - all sides, any damage etc


Photo 1


Photo 2


Photo 3


Photo 4


Photo 5


Photo 6

Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name BRANDON PERRY

Engineers signature



6 Oct 2026 11:44 AM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6