



CERTIFICATE OF EXAMINATION

ROR 21

Complete

Score	56 / 56 (100%)	Flagged items	0	Actions	0
-------	----------------	---------------	---	---------	---

Site conducted

Ashvale Head Office

Conducted on

28 Mar 2025 2:01 PM UTC

Prepared by

Munyaradzi

Location

Firbank Industrial Estate, Dallow
Rd, Luton LU1 1TW, UK
(51.884217299999996,
-0.4442659)

Asset

ROR 21
Roller - Hamm HD 8VV 80 Roller

Asset serial number

WGH0H199JHAA05624

Asset hours

0773

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4

Power unit	11 / 11 (100%)
Oil level	Acceptable
Water/Antifreeze level	Acceptable
Belt tension/Condition	Acceptable
Mountings	Acceptable
Emissions/Exhaust	Acceptable
Oil leaks	Acceptable
Hoses & pipes	Acceptable
Gauges/Warning indicators	Acceptable
Turbo	N/A
Air cleaner/Indicator	Acceptable
Spark Arrestor	N/A

Transmission	5 / 5 (100%)
Oil levels/Leaks	Acceptable
Controls/Operations	Acceptable
Drive shafts/Axles	N/A
Hub reduction units/levels	Acceptable
Transfer box/levels	N/A

Brakes	5 / 5 (100%)
Air/Hydraulic leaks	Acceptable
Drums/Discs/Pads/Shoes	N/A
Foot/Hand controls	Acceptable
Cables/Rods/Pipes	Acceptable
Fluid levels/Efficiency	Acceptable

Steering	6 / 6 (100%)
Box/Column/Wheel	Acceptable
King Pins/Bushes	N/A
Ramp/Pump/Hoses	Acceptable
Track Rods/Steering Arms	Acceptable
Linkages/Ball joints	N/A
Oil levels/Leakes	Acceptable

Running Gear		5 / 5 (100%)
Tyres/Wheels/Tracks		N/A
Wheel bearings		N/A
Axle security		N/A
Over run brake rods/cable		N/A
Towing/Frame Attachments		N/A

Fuel System		4 / 4 (100%)
Fuel tank/Security		Acceptable
Fuel line/leaks		Acceptable
Filters/Pumps		Acceptable
Fuel level/Gauge		Acceptable

Hydraulics		5 / 5 (100%)
Rams		Acceptable
Pumps/Hoses/Pipes		Acceptable
Safety indicators		Acceptable
Oil levels/leaks		Acceptable
Controls		Acceptable

Electrical	10 / 10 (100%)
Battery	Acceptable
Alternator/Charging	Acceptable
Wiring	Acceptable
Fuses/Circuit breakers	Acceptable
Lights/Indicators	Acceptable
Warning Indicators	Acceptable
Outlet sockets	N/A
Limit/Proximity switches	N/A
Safety Devices	Acceptable
Warning Devices	Acceptable

Cab		5 / 5 (100%)
Seating/Belts		Acceptable
Structure/Rops		N/A
Glass/Mirrors		N/A
Mountings		N/A
Safe access to components, struts and hinges all in working order		Yes

Sign off

Engineers name & signature



munyaradzi
28 Mar 2025 2:08 PM UTC

Media summary



Photo 1



Photo 2



Photo 3



Photo 4