

## RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT AND EQUIPMENT

IN ACCORDANCE WITH THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

|                                                                                                                |                                                                                                                                                                                                                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                                                                                                                | Diesel Hydraulic Excavator                                                                                                                                                                                                                                                                                                             |
| Description of equipment                                                                                       | Doosan DX140LC-7                                                                                                                                                                                                                                                                                                                       |
| Identification mark of equipment                                                                               | Pno ASH 1417 Sno DXCCEBEYEP0020077                                                                                                                                                                                                                                                                                                     |
| Quick Hitch                                                                                                    | 105507                                                                                                                                                                                                                                                                                                                                 |
| Name and address of owner of equipment                                                                         | Ashvale Plant Hire Ltd<br>Firbank Trading Estate<br>Luton<br>LU1 1TD                                                                                                                                                                                                                                                                   |
| Date of the last thorough examination and identification of the record issued on that occasion                 | May 2024                                                                                                                                                                                                                                                                                                                               |
| Safe working load or loads and (where relevant) corresponding radii                                            | Refer to Manufacturers Lifting Charts & Radii Tables                                                                                                                                                                                                                                                                                   |
| Details of any defects found (if none state NONE)                                                              | None                                                                                                                                                                                                                                                                                                                                   |
| Date(s) by which defects described above must be rectified                                                     |                                                                                                                                                                                                                                                                                                                                        |
| What parts if any were inaccessible?<br>(TO BE COMPLETED ONLY AFTER A THOROUGH EXAMINATION OF A HOIST OR LIFT) | N/A                                                                                                                                                                                                                                                                                                                                    |
| Latest date by which the next thorough examination must be carried out                                         | 10th April 2026                                                                                                                                                                                                                                                                                                                        |
| Examined at                                                                                                    | Lodge Park, Wintringham Park, St Neots, PE19 0AT                                                                                                                                                                                                                                                                                       |
| Other notes                                                                                                    | Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables. |

### Declaration

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on **10/04/2025** and that the above particulars are correct.

### Signature or other identification



Allen Lee. Engineering Surveyor

Name and address of person authenticating the record and responsible for the thorough examination.

Sky Technical Services Ltd

4 Victoria Cottages

Love Lane, Mayfield, E.Sussex. TN20 6EN

Tel 01435 873355 / 07703 292932.

Email [info@skytechnical.co.uk](mailto:info@skytechnical.co.uk)

**Date the record is made** 10/04/2025