



Record Of Thorough Examination Of Lifting Plant & Equipment

Ash 48

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
-------	------------	---------------	---	---------	---

000006

Conducted on 2 Jun 2026 1:18 PM BST

Prepared by Andrew Gibbins

Location 8 Gudgeon Mdw, Arlesey SG15
6AX, UK
(52.0163337, -0.2652826)

Asset Ash 48
3 Ton Excavator - Excavator (mini)
Kubota KX027-4

Asset serial number KBCGJ11BLPZK60812

Identification mark of quick hitch & model Whites

Date of the last thorough examination 05/06/2025

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE) None

Date(s) by which defects described above must be rectified Na

Latest date by which the next thorough examination must be carried out 2 Jun 2027 1:21 PM BST

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name

Andrew Gibbins

Engineers signature



2 Jun 2026 1:22 PM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5