



Record Of Thorough Examination Of Lifting Plant & Equipment

ASH 945

Complete

Score	0 / 0 (0%)	Flagged items	0	Actions	0
-------	------------	---------------	---	---------	---

000025

Conducted on 7 Aug 2026 10:17 AM BST

Prepared by Brandon Perry

Location 13 Rainbow Cl, Bedford MK45 3QN, UK

Asset ASH 945
9 Ton Dumper - Dumper 9T
Thwaites MACH 2290

Asset serial number SLCM22902416G5150

Identification mark of quick hitch & model

Date of the last thorough examination 07/08/2026

Safe Working load or loads (where relevant) corresponding radii - please refer to Manufacturers Lifting Charts & Radii Tables

Details of any defects found (if none state NONE) None

Date(s) by which defects described above must be rectified

Latest date by which the next thorough examination must be carried out 7 Aug 2027 10:19 AM BST

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12




Photo 13

Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Sign off

Declaration I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above and that the above particulars are correct.

Engineers name Brandon Perry

Engineers signature



7 Aug 2026 10:21 AM BST

Ashvale Plant Hire Ltd | Ashvale House | Toddington Road | Westoning | Beds | MK45 5AH

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12



Photo 13