

RECORD OF THOROUGH EXAMINATION OF LIFTING PLANT AND EQUIPMENT

IN ACCORDANCE WITH THE LIFTING OPERATIONS AND LIFTING EQUIPMENT REGULATIONS 1998 (LOLER)

	Diesel Hydraulic Excavator
Description of equipment	KUBOTA KX027-4
Identification mark of equipment	Pno ASH 50 Sno 61794
Name and address of owner of equipment	Ashvale Plant Hire Ltd Firbank Trading Estate Luton LU1 1TD
Date of the last thorough examination and identification of the record issued on that occasion	Not Known
Safe working load or loads and (where relevant) corresponding radii	Refer to Manufacturers Lifting Charts & Radii Tables
Details of any defects found (if none state NONE)	None
Date(s) by which defects described above must be rectified	
What parts if any were inaccessible? (TO BE COMPLETED ONLY AFTER A THOROUGH EXAMINATION OF A HOIST OR LIFT)	N/A
Latest date by which the next thorough examination must be carried out	14 th October 2026
Examined at	Cromwell Place, Fisherswood Rd, Wixams, MK45 3QZ
Other notes	Always ensure that the correct operators instructions are with the machine and that the correct SWL is clearly visible. Where a quickhitch is fitted ensure that the operator understands the procedures and is competent to operate the hitch safely. For full SWL specifications always refer to manufacturers lifting/radii tables.

Declaration

I hereby declare that the equipment described in this record was thoroughly examined in accordance with the appropriate provisions and found free from any defect likely to affect safety other than those listed above on **14/10/2025** and that the above particulars are correct.

Signature or other identification



Allen Lee. Engineering Surveyor

Name and address of person authenticating the record and responsible for the thorough examination.

Sky Technical Services Ltd
4 Victoria Cottages

Love Lane, Mayfield, E.Sussex. TN20 6EN .

Tel 01435 873355 / 07703 292932.

Email info@skytechnical.co.uk

Date the record is made 14/10/2025