



2.CERTIFICATE OF EXAMINATION

RAM 02

Complete

| | | | | | |
|--------------|----------------|----------------------|---|----------------|---|
| Score | 56 / 56 (100%) | Flagged items | 0 | Actions | 0 |
|--------------|----------------|----------------------|---|----------------|---|

Site conducted Ashvale Head Office

Conducted on 24 Feb 2026 2:29 PM GMT

Prepared by B.P

Location Sunnyside, Toddington Road
Bedford
England
MK45 5AH
United Kingdom
(51.97269839829287,
-0.5073508578836498)

Asset RAM 02
Roller - Bomag BMP8500 trench roller

Asset serial number N/A

Asset hours 546

Supply multiple photo's of asset - all sides, any damage etc



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8

| Power unit | 11 / 11 (100%) |
|---------------------------|----------------|
| Oil level | Acceptable |
| Water/Antifreeze level | Acceptable |
| Belt tension/Condition | Acceptable |
| Mountings | Acceptable |
| Emissions/Exhaust | Acceptable |
| Oil leaks | Acceptable |
| Hoses & pipes | Acceptable |
| Gauges/Warning indicators | Acceptable |
| Turbo | Acceptable |
| Air cleaner/Indicator | Acceptable |
| Spark Arrestor | Acceptable |

| | |
|-----------------------------------|--------------|
| Transmission | 5 / 5 (100%) |
| Oil levels/Leaks | Acceptable |
| Controls/Operations | Acceptable |
| Drive shafts/Axles | Acceptable |
| Hub reduction units/levels | Acceptable |
| Transfer box/levels | Acceptable |

| | |
|--------------------------------|--------------|
| Brakes | 5 / 5 (100%) |
| Air/Hydraulic leaks | Acceptable |
| Drums/Discs/Pads/Shoes | Acceptable |
| Foot/Hand controls | Acceptable |
| Cables/Rods/Pipes | Acceptable |
| Fluid levels/Efficiency | Acceptable |

| | |
|---------------------------------|--------------|
| Steering | 6 / 6 (100%) |
| Box/Column/Wheel | Acceptable |
| King Pins/Bushes | Acceptable |
| Ramp/Pump/Hoses | Acceptable |
| Track Rods/Steering Arms | Acceptable |
| Linkages/Ball joints | Acceptable |
| Oil levels/Leakes | Acceptable |

| | |
|----------------------------------|--------------|
| Running Gear | 5 / 5 (100%) |
| Tyres/Wheels/Tracks | Acceptable |
| Wheel bearings | Acceptable |
| Axle security | Acceptable |
| Over run brake rods/cable | Acceptable |
| Towing/Frame Attachments | Acceptable |

| | |
|---------------------------|--------------|
| Fuel System | 4 / 4 (100%) |
| Fuel tank/Security | Acceptable |
| Fuel line/leaks | Acceptable |
| Filters/Pumps | Acceptable |
| Fuel level/Gauge | Acceptable |


| | |
|--------------------------|--------------|
| Hydraulics | 5 / 5 (100%) |
| Rams | Acceptable |
| Pumps/Hoses/Pipes | Acceptable |
| Safety indicators | Acceptable |
| Oil levels/leaks | Acceptable |
| Controls | Acceptable |

| | |
|---------------------------------|----------------|
| Electrical | 10 / 10 (100%) |
| Battery | Acceptable |
| Alternator/Charging | Acceptable |
| Wiring | Acceptable |
| Fuses/Circuit breakers | Acceptable |
| Lights/Indicators | Acceptable |
| Warning Indicators | Acceptable |
| Outlet sockets | Acceptable |
| Limit/Proximity switches | Acceptable |
| Safety Devices | Acceptable |
| Warning Devices | Acceptable |

| | |
|--|--------------|
| Cab | 5 / 5 (100%) |
| Seating/Belts | Acceptable |
| Structure/Rops | Acceptable |
| Glass/Mirrors | Acceptable |
| Mountings | Acceptable |
| Safe access to components, struts and hinges all in working order | Yes |

Sign off

Engineers name & signature

A handwritten signature in black ink, appearing to read 'Brandon Perry', written over a light gray rectangular background.

Brandon Perry
24 Feb 2026 2:32 PM GMT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8